



CONNECTION GUIDE

For Windows PC and Mac

- 1 Connect the ECOH Link to your PC or Mac via USB



- 2 The ECOH Link will flash blue and automatically launch the driver

- If AutoPlay is disabled, go to the file manager, select This PC, double click on USBDisplay under drives, and double click Launcher
- When the ECOH Link has a solid blue circle, you are ready to present

- 3 Press the ECOH Link button to share your screen

