

IPX Series

Firmware Release Notes

Released 04.2022

Release version 1.6.4 contains the following updates:

Features

- Further improvements on response time to start and stop audio messages
- The Half Duplex Intercom feature in InformaCast Advanced will no longer be supported in IPX firmware versions 1.6.4 and above. If help is needed setting up Full Duplex Intercom with InformaCast Advanced, please contact AtlasIED Tech Support for assistance.

Bugs

- Additional bug fixes and performance improvements

List of Known Issues

- Auto-provisioning is not currently activated

Note: The default password for units on Firmware Versions 1.6.0 and above has been updated to last 6 digits of Mac address to comply with State of California SB-327

Firmware Update Instructions

Note: IPX endpoints on any firmware version prior to 1.0.9 will need to update to version 1.0.9 before updating to version 1.3.1.

IPX endpoints on any firmware version between 1.0.9 and 1.3.0 will need to be updated to version 1.3.1 prior to updating to version 1.6.4.

IPX endpoints on firmware version 1.3.1 or higher can be updated directly to firmware version 1.6.4.

Note: When updating IPX endpoints, AtlasIED recommends using the AtlasIED Discover Application.

Firmware version 1.0.9 (Build# 530) is the minimum required version for update with AtlasIED Discover Application.

Firmware version 1.2.0 is the minimum required version for updating from the WebUI.

IMPORTANT: Do NOT reboot the device during this process until it is fully updated. Multiple reboots may occur automatically as the endpoint installs firmware.

Updating Firmware with the AtlasIED Discover Application

1. Download the AtlasIED Discover Quick Start Guide
 - i. The AtlasIED Discover Quick Start Guide can be accessed through the following link
<http://mitk.co/NLD>
2. Download the AtlasIED Discover App IPX Firmware 1.6.4 File
 - i. The AtlasIED Discover App IPX Firmware 1.6.4 can be accessed through the following link
<http://mitk.co/NLE>
3. Follow the instructions found in the AtlasIED Discover Quick Start Guide.

For additional support AtlasIED Tech Support can be reached at 1-800-876-3333 or www.atlasied.com/support